

Contents

<i>Preface</i>	page iii
<i>List of tables</i>	xiii
<i>Notation</i>	xiv

Part I Basic Thermodynamics and Kinetics of Phase Transformations

1 Introduction	3
1.1 What Is a Phase Transition?	3
1.2 Atoms and Materials	4
1.3 Pure Elements	6
1.4 Alloys – Unmixing and Ordering	9
1.5 Transitions and Transformations	12
1.6 Brief Review of Thermodynamics and Kinetics	15
Problems	19
2 Essentials of T-c Phase Diagrams	21
2.1 Overview of the Approach	21
2.2 Intuition and Expectations about Alloy Thermodynamics	23
2.3 Free Energy Curves, Solute Conservation, and the Lever Rule	27
2.4 Common Tangent Construction	30
2.5 Continuous Solid Solubility Phase Diagram	32
2.6 Solid Solutions	33
2.7 Unmixing Phase Diagrams	38
2.8 Eutectic and Peritectic Phase Diagrams	41
2.9 Ternary Phase Diagrams	45
2.10 Long-Range Order in the Point Approximation	47
2.11 Alloy Phase Diagrams	51
Problems	53
3 Diffusion	56
3.1 The Diffusion Equation	57
3.2 Gaussian and Error Function Solutions to the 1D Diffusion Equation	61
3.3 Fourier Series Solutions to the Diffusion Equation	66

3.4	Bessel Functions and other Special Function Solutions to the Diffusion Equation	71
3.5	Kinetic Master Equation and Equilibrium	74
3.6	Linear Kinetic Response	76
	Problems	77
4	Nucleation	80
4.1	Terminology and Issues	81
4.2	Critical Nucleus	82
4.3	Heterogeneous Nucleation	85
4.4	Free Energy Curves, Elastic Energy	88
4.5	The Nucleation Rate	91
4.6	Time-Dependent Nucleation	98
	Problems	101
5	Effects of Diffusion and Nucleation on Phase Transformations	103
5.1	Non-Equilibrium Processing of Materials	104
5.2	Alloy Solidification with Solute Partitioning	107
5.3	Alloy Solidification – Suppressed Diffusion in the Solid Phase	108
5.4	Alloy Solidification – Suppressed Diffusion in the Solid and Liquid	113
5.5	Practical Issues for Alloy Solidification and Evaporation	115
5.6	Heat Flow and Kinetics	117
5.7	Nucleation Kinetics	119
5.8	Glass Formation	120
5.9	Solid-State Amorphization and Suppressed Diffusion in a Solid Phase	122
5.10	Reactions at Surfaces	124
5.11	The Glass Transition	129
	Problems	131
	 Part II The Atomic Origins of Thermodynamics and Kinetics	 135
6	Energy	137
6.1	Molecular Orbital Theory of Diatomic Molecules	137
6.2	Electronic Energy Bands in Solids	144
6.3	Elastic Constants and the Interatomic Potential	156
6.4	Linear Elasticity	160
6.5	Misfitting Particle	164
6.6	Surface Energy	169
	Problems	172

7 Entropy	175
7.1 Static and Dynamic Sources of Entropy	176
7.2 Short-Range Order and the Pair Approximation	177
7.3 Local Atomic Structures Described by Clusters	181
7.4 Thermodynamics with Cluster Approximations	183
7.5 Concept of Vibrational Entropy	185
7.6 Phonon Statistics	188
7.7 Lattice Dynamics and Vibrational Entropy	190
7.8 Bond Proportion Model	193
7.9 Bond-Stiffness-versus-Bond-Length Model	201
Problems	204
8 Pressure	208
8.1 Materials under Pressure at Low Temperatures	208
8.2 Thermal Pressure, a Step Beyond the Harmonic Model	213
8.3 Free Energies and Phase Boundaries under Pressure	215
8.4 Chemical Bonding and Antibonding under Pressure	217
8.5 Two-Level System under Pressure	220
8.6 Activation Volume	223
Problems	224
9 Atom Movements with the Vacancy Mechanism	226
9.1 Random Walk and Correlations	226
9.2 Phenomena in Alloy Diffusion	235
9.3 Diffusion in a Potential Gradient	244
9.4 Non-Thermodynamic Equilibrium in Driven Systems	248
9.5 Vineyard's Theory of Diffusion	252
Problems	258
Part III Types of Phase Transformations	261
10 Melting	263
10.1 Free Energy and Latent Heat	263
10.2 Chemical Trends of Melting	264
10.3 Free Energy of a Solid	265
10.4 Entropy of a Liquid	273
10.5 Thermodynamic Condition for T_m	276
10.6 Glass Transition	278
10.7 Two Dimensions	281
Problems	283
11 Transformations Involving Precipitates and Interfaces	285
11.1 Guinier–Preston Zones	285

11.2	Surface Structure and Thermodynamics	287
11.3	Surface Structure and Kinetics	293
11.4	Chemical Energy of a Precipitate Interface	296
11.5	Elastic Energy and Shape of Growing Precipitates	298
11.6	Precipitation at Grain Boundaries and Defects	301
11.7	The Eutectoid Reaction and Ferrous Metallurgy	304
11.8	The Kolmogorov-Johnson-Mehl-Avrami Growth Equation	310
11.9	Coarsening	313
	Problems	316
12	Spinodal Decomposition	318
12.1	Concentration Fluctuations and the Free Energy of Solution	318
12.2	Adding a Square Gradient Term to the Free Energy $F(c)$	320
12.3	Constrained Minimization of the Free Energy	325
12.4	The Diffusion Equation	330
12.5	Effects of Elastic Strain Energy	332
	Problems	335
13	Phase Field Theory	336
13.1	Spatial Distribution of Phases and Interfaces	336
13.2	Solidification	339
13.3	Ginzburg-Landau Equation and Order Parameters	341
13.4	Interfaces Between Domains	344
	Problems	353
14	Method of Concentration Waves and Chemical Ordering	354
14.1	Structure in Real Space and Reciprocal Space	354
14.2	Symmetry and the Star	361
14.3	The Free Energy in k -Space with Concentration Waves	364
14.4	Symmetry Invariance of Free Energy and Landau-Lifshitz Rule for Second-Order Phase Transitions	368
14.5	Thermodynamics of Ordering in the Mean Field Approximation with Long-Range Interactions	372
	Problems	377
15	Diffusionless Transformations	379
15.1	Dislocations and Mechanisms	380
15.2	Twinning	385
15.3	Martensite	387
15.4	The Crystallographic Theory of Martensite	393
15.5	Landau Theory of Displacive Phase Transitions	396
15.6	First-Order Landau Theory	401
15.7	Phonons and Structural Collapse	403
15.8	Soft Phonons in BCC Structures	404

Problems	408
16 Thermodynamics of Nanomaterials	410
16.1 Grain Boundary Structure	411
16.2 Grain Boundary Energy	412
16.3 Gibbs–Thomson Effect	415
16.4 Energies of Free Electrons Confined to Nanostructures	417
16.5 Configurational Entropy of Nanomaterials	419
16.6 Vibrational Entropy	422
16.7 Gas Adsorption	424
16.8 Characteristics of Magnetic Nanoparticles	427
16.9 Elastic Energy of Anisotropic Microstructures	429
Problems	431
17 Magnetic and Electronic Phase Transitions	433
17.1 Overview of Magnetic and Electronic Phase Transitions	434
17.2 Exchange Interactions	439
17.3 Correlated Electrons	443
17.4 Thermodynamics of Ferromagnetism	446
17.5 Spin Waves	450
17.6 Thermodynamics of Antiferromagnetism	452
17.7 Ferroelectric Transition	456
17.8 Domains	458
Problems	460
18 Phase Transitions in Quantum Materials	462
18.1 Bose-Einstein Condensation	462
18.2 Superfluidity	465
18.3 Condensate Wavefunction	468
18.4 Superconductivity	471
18.5 Quantum Critical Behavior	480
Problems	483
 Part IV Advanced Topics	 485
19 Low Temperature Analysis of Phase Boundaries	487
19.1 Ground State Analysis for $T = 0$	488
19.2 Richards, Allen, Cahn Ground State Maps	490
19.3 Low, but Finite Temperatures	490
19.4 Analysis of Equiatomic bcc Alloys	496
19.5 High Temperature Expansion of the Partition Function	497
Problems	499

20 Cooperative Behavior Near a Critical Temperature	501
20.1 Critical Exponents	502
20.2 Critical Slowing Down	502
20.3 The Rushbrooke Inequality	504
20.4 Scaling Theory	505
20.5 Scaling and Decimation	507
20.6 Partition Function for One-Dimensional Chain	508
20.7 Partition Function for Two-Dimensional Lattice	512
Problems	516
21 Elastic Energy of Solid Precipitates	517
21.1 Transformation Strains and Elastic Energy	518
21.2 Real Space Approach	520
21.3 k -Space Approach	522
Problems	525
22 Statistical Kinetics of Ordering Transformations	527
22.1 Ordering Transformations with Vacancies	528
22.2 B2 Ordering with Vacancies in the Point Approximation	530
22.3 Vacancy Ordering	535
22.4 Kinetic Paths	536
Problems	542
23 Diffusion, Dissipation, and Inelastic Scattering	544
23.1 Atomic Processes and Diffusion	544
23.2 Dissipation and Fluctuations	548
23.3 Inelastic Scattering	551
23.4 Phonons and Quantum Mechanics	554
Problems	558
24 Vibrational Thermodynamics of Materials at High Temperatures	559
24.1 Lattice Dynamics	560
24.2 Harmonic Thermodynamics	565
24.3 Quasiharmonic Thermodynamics	566
24.4 Thermal Effects Beyond Quasiharmonic Theory	569
24.5 Anharmonicity and Phonon-Phonon Interactions	571
24.6 Electron-Phonon Interactions and Temperature	575
Problems	577
<i>Further Reading</i>	579
<i>References</i>	583
<i>Index</i>	595